

## Fittings

The use of anaerobic resins as a sealant for threaded joints is strictly forbidden.

### REDUCING TEES 90°

#### > SOCKET

	Ø/ØR	Pack	Ref.
	25/20	S10*	FTR2520
	32/20	S10*	FTR3220
	32/25	S10*	FTR3225
	40/20	S10*	FTR4020
	40/25	S10*	FTR4025
	40/32	S10*	FTR4032
	50/20	S10*	FTR5020
	50/25	S10*	FTR5025
	50/32	S10*	FTR5032
	50/40	S10*	FTR5040
	63/20	1	FTR6320
63/25	1	FTR6325	


FTR4025

	Ø	Pack	Ref.
	63/32	1	FTR6332
	63/40	1	FTR6340
	63/50	1	FTR6350
	75/25	1	FTR7525
	75/40	1	FTR7540
	75/63	1	FTR7563
	90/25	1	FTR9025
	90/40	1	FTR9040
	90/75	1	FTR9075
	110/32	1	FTR1132
	110/50	1	FTR1150
110/90	1	FTR1190	

FTR1132

### 3 PIECE UNIONS


#### > SOCKET/SOCKET - WITH EPDM GASKET

	Ø	Pack	Ref.
	20	S10*	F3P20
	25	S10*	F3P25
	32	S10*	F3P32
	40	S10*	F3P40
	50	S10*	F3P50
	63	1	F3P63

F3P50

### 3 PIECE UNIONS KRYOCLIM® BRASS


#### > SOCKET - FEMALE BRASS THREAD, WITH EPDM GASKET

	Ø x G	Pack	Ref.
	20 x 1/2"	1	F3G/L20
	25 x 3/4"	1	F3G/L25
	32 x 1"	1	F3G/L32
	40 x 1 1/4"	1	F3G/L40
	50 x 1 1/2"	1	F3G/L50
	63 x 2"	1	F3G/L63


F3G/L32

### PIECE UNIONS KRYOCLIM® BRASS

#### > SOCKET - MALE BRASS THREAD, WITH EPDM GASKET

	Ø x f	Pack	Ref.
	20 x 1/2"	1	F3F/L20
	25 x 3/4"	1	F3F/L25
	32 x 1"	1	F3F/L32

F3F/L32

	Ø x f	Pack	Ref.
	40 x 1 1/4"	1	F3F/L40
	50 x 1 1/2"	1	F3F/L50
	63 x 2"	1	F3F/L63


F3F/L32

## Threaded fittings

For high torque.

### THREADED ADAPTORS


#### > SOCKET/SPIGOT - FEMALE BRASS THREAD

	Ø x G	Pack	Ref.
	20/25 x 1/2"	S5*	FMML20
	25/32 x 3/4"	S5*	FMML25
	32/40 x 1"	S5*	FMML32
	40/50 x 1 1/4"	1	FMML40
	50/63 x 1 1/2"	1	FMML50
	63/75 x 2"	1	FMML63
	75/90 x 2 1/2"	1	FMML75
	90/110 x 3"	1	FMML90

FMML40

### ADAPTOR NIPPLES

#### > SOCKET/SPIGOT - MALE BRASS THREAD

	Ø x f	Pack	Ref.
	20/25 x 1/2"	S5*	FEAL20
	25/32 x 3/4"	S5*	FEAL25
	32/40 x 1"	S5*	FEAL32
	40/50 x 1 1/4"	1	FEAL40
	50/63 x 1 1/2"	1	FEAL50
	63/75 x 2"	1	FEAL63
	75/90 x 2 1/2"	1	FEAL75
	90/110 x 3"	1	FEAL90

FEAL40